2020-2024 Cadillac CT4 - Cabin Air Filter

2020-2024 Cadillac CT4 | Easy | 15-20 minutes | $28 DIY

TOOLS
Flashlight Rag for wiping the housing mouth

PARTS
Cabin air filter for 2020-2024 Cadillac CT4; verify arrows, size, and VIN/trim fitment $28.00

STEPS

1. **Confirm the filter location on the CT4 - On every 2020-2024 CT4 the cabin filter is** behind the glove box. The 2.0L and 2.7L turbos share the same filter and access; the cartridge is the same GM part used across the ATS, CT5, CT6, XT4, XT5, and XT6.
2. **Kill the ignition and empty the glove box - Turn the car fully off and remove everything** from the glove box. The CT4's dash trim around the box is soft-touch and scratches easily, so clear the box fully and move the passenger seat back for a comfortable working angle.
3. **Detach the damper and drop the glove box - Open the glove box and find the damper arm.** Unclip it from its post and let it hang. Press both side walls inward so the stops clear, and lower the box onto its hinges - don't pull it off.
4. **Remove the small filter access panel - Behind the lowered glove box: a small rectangular** access panel on the HVAC housing with latch tabs on its sides. Press the tabs and pull the panel off. A flashlight helps - it sits deep enough to disappear in shadow.
5. **Pull the old cartridge and read its arrow - Slide the old filter straight out and read** the airflow arrow - it points down toward the blower motor. These cartridges come out surprisingly dirty in city driving, so compare old and new side by side before you toss it.
6. **Install the new filter arrow-down - Slide the new filter in the same orientation, airflow** arrow pointing down toward the blower. Push it fully in until flush, then press the access panel back on until its tabs latch. Both sides must click or the fan whistles.
7. **Reassemble and test the HVAC - Swing the glove box up, squeeze the sides in so the stop** tabs catch, and clip the damper arm back onto its post. Start the car, fan on high, recirculate - strong airflow, no whistling, no odor. Replace yearly or every 12,000-15,000 mil...

TORQUE

ezcarfix.com