2015-2022 Chevrolet Trax - Wiper Blade Replacement

2015-2022 Chevrolet Trax | Easy | 15-20 minutes | $81 DIY

TOOLS

Microfiber cloth Glass cleaner Folded bath towel (arm cushion)

PARTS

Driver wiper blade, 26" Bosch 26A $32.99
Passenger wiper blade, 14" Bosch 14B $32.99
Rear wiper blade, 10" $14.99

STEPS

1. **Confirm sizes and buy the right blades - The 2015-2022 Trax takes 26-inch driver, 14-inch** passenger, and 10-inch rear blades. Fronts use a pinch-tab (19mm top-lock) connector - buy beam-style blades with that adapter included. Hold each new blade next to the old one to confirm...
2. **Park and prep the vehicle - Park on level ground, ignition off - no service mode needed,** just lift the arms off the glass. Lay a folded towel across the lower windshield, and clean the glass so grit doesn’t drag under the new blades.
3. **Release the old driver-side blade - Lift the driver arm upright and find the pinch-tab** housing. Squeeze both tabs and slide the blade off the pin - or press the push-button tab if yours has one. Keep your other hand on the arm.
4. **Prep the new driver-side blade - Peel the protector off the rubber edge - it streaks if** left on. Confirm the adapter is the pinch-tab/top-lock piece, not a J-hook one. Lay the new blade next to the old one to confirm length and check the rubber for kinks.
5. **Install the new driver-side blade and check the lock - Slide the connector onto the pin** until the tabs snap - you should hear a distinct click. Tug firmly; blade and arm should move as one piece. Lower the arm onto the windshield, then repeat the tug test.
6. **Passenger side and rear blade - Passenger side installs the same way: lift, squeeze tabs,** slide the old off, click the new on. For the rear, lift the arm, press the tab at the blade’s base, slide it off, and thread the new 10-inch blade on until it clicks.
7. **Test with washer fluid and troubleshoot - Run the washers and let all three blades sweep** several times - every pass should be smooth and streak-free. Chatter means the adapter isn’t seated; pop it off and re-click it. A thin line of water usually means a shipping protector was l...

ezcarfix.com