2014-2021 Toyota Tundra - Wiper Blade Replacement

2014-2021 Toyota Tundra | Easy | 10-15 minutes | $66 DIY

TOOLS

tape measure (confirm 26" / 22" - 2014-2015 passenger side is disputed in charts)
clean rag folded towel (to protect the glass)

PARTS

Driver wiper blade, 26" Bosch 26A $32.99
Passenger wiper blade, 22" Bosch 22B $32.99

STEPS

1. **Confirm the sizes and buy pinch-tab blades - The 2014-2021 Tundra takes 26 inches** driver’s side, 22 inches passenger’s side - measure the old passenger blade first; charts disagree for some years. This truck does NOT use J-hooks: its arms use a pinch-tab connector, so buy pinch-t...
2. **Stop the wipers mid-sweep and lift the arms - Turn the wipers on, then kill the ignition** with the blades halfway up - that parks the arms within reach. Lift the driver’s arm until it stands. The long arms are strongly sprung, so lift with a steady hand.
3. **Remove the old driver’s-side blade - Squeeze the two pinch tabs and slide the blade off** the arm. Towel on the windshield under the arm immediately - a bare Tundra arm snapping back onto that big glass is a costly mistake.
4. **Prep the new blade - Unbox the 26-inch blade and strip the edge protector. If** multi-adapter, swap to the pinch-tab adapter per the blade’s instructions and click it into the center. Wipe the rubber and compare against the old blade: 26 inches, pinch-tab connec...
5. **Install the new blade and verify the lock - Slide the pinch-tab connector onto the arm** until the tabs snap. This connector can feel seated when it isn’t - pull down firmly and twist it; no play allowed. Lower the arm by hand and check the rubber lies flat.
6. **Passenger side with the 22-inch blade (pickup - no rear wiper) - Same pinch-tab routine** on the passenger side with the 22-inch blade: squeeze, slide off, click on, tug-test. The pickup has no rear wiper, so you’re done. Clear the wiper tray - debris migrates onto the blade edge.
7. **Test with washer fluid - Ignition on, run the washers, and watch both blades. Clean,** quiet arcs, no chatter, no missed bands. If a blade chatters, the pinch tabs aren’t fully locked - reseat it. Top off the washer reservoir; the windshield eats fluid fast.

ezcarfix.com