# 2023-2026 Acura Integra - Wiper Blade Replacement



**2023-2026 Acura Integra | Easy | 10-15 minutes | $66 DIY**

**TOOLS**
Tape measure (to confirm the passenger blade length)  Microfiber cloth

**PARTS**
Driver wiper blade, 24" Bosch 24A $32.99
Passenger wiper blade, 19" Bosch 19B $32.99

## STEPS

1. **Confirm the sizes and buy the blades - 24-inch driver, 19-inch passenger - widely** confirmed, though one chart lists 18 inches, so measure your old passenger blade first. No rear wiper. The front arms use a 16mm top-button (side-press) connector - buy top-button blades, not...
2. **Move the wipers to the maintenance position - Wipers park tucked below the hood line -** raise them first. Switch to ON without starting the engine, then back OFF; within ten seconds, pull the wiper switch to MIST and hold two seconds - the arms sweep up and stop partway.
3. **Release the old driver-side blade - Fold the driver-side arm away from the glass until it** holds. Press the side-press button on the center connector and slide the blade down off the arm. Hold the bare arm - it can snap back and crack the windshield.
4. **Prep the new 24-inch blade - Pull the protective sleeve off and don’t touch the rubber** wiping edge. Confirm the top-button adapter is already fitted. Compare the new 24-inch blade against the old one to confirm the length before mounting.
5. **Slide the new blade on and lock it - Slide the new 24-inch blade onto the arm until the** side-press button clicks. Tug it firmly - completely immobile means locked. If it slides, reseat it until the click is unmistakable. Lower the arm gently onto the glass.
6. **Install the 19-inch passenger blade - Repeat the button-release and install for the** passenger-side blade, confirming the length against your old blade (19 inches on the consensus, 18 on one chart). No rear wiper - the two fronts complete the replacement. Fold both arms back...
7. **Exit maintenance position and test - Switch the vehicle on and run the wipers once. Spray** washer fluid and watch a full sweep on low and high for streaks or chattering. Re-seat any chattering blade - the clip didn’t fully engage.

ezcarfix.com