2022-2026 BMW i4 - Wiper Blade Replacement

2022-2026 BMW i4 | Easy | 15-20 minutes for both front blades | $66 DIY

TOOLS

Tape measure or ruler Microfiber cloth and glass cleaner Washer fluid (to top up the reservoir)

PARTS

Driver wiper blade, 24" Bosch 24A $32.99
Passenger wiper blade, 19" Bosch 19B $32.99

STEPS

1. **Confirm the blade sizes - 24 inches and 19 inches - i4: 24-inch (600 mm) driver blade,** 19-inch (475 mm) passenger blade. Some charts list 18 inches for the passenger side - it fits but leaves a narrower swept area, so measure the old blade first. No rear wiper on the i4.
2. **Put the wipers in the fold-out position - Standby (ignition on), press-hold the wiper** stalk down until the wipers stop near-vertical - they park under the hood lip. Fold each arm out. To repark: arms onto the glass, standby, press-hold the stalk down. Never force the arms up; th...
3. **Remove the old driver-side blade from its pinch-tab connector - Hold the arm steady,** squeeze both tabs on the connector housing, and slide the blade straight down off the arm’s pin. Note the housing’s orientation for the reinstall. Squeeze firmly and slide straight - rocking sideways can crack the ho...
4. **Install the new 24-inch driver-side blade - Slide the new 24-inch blade’s housing up the** arm until both tabs click outward - two distinct clicks. Tug the blade firmly along the arm; a half-seated tab releases the first time the wipers change direction at speed. Fold the arm gently...
5. **Replace the 19-inch passenger-side blade - Repeat on the passenger arm with the new** 19-inch blade. Double-check it’s the 19-inch (475 mm) blade, not the 24-inch driver blade - too long, it will collide with the driver blade or A-pillar trim. Seat the arm back on the glass.
6. **Clean the windshield and check the arm ends - Clean the swept area with glass cleaner and** a microfiber - grime film where blades park makes new blades chatter. Inspect both arms and housings for twists, cracked plastic, or bent pins. Top up washer fluid (BMW concentrate) under the h...
7. **Park the wipers and test the new blades - Repark the wipers, then run the washers and** test low and high speeds - clearing must be silent with no streaks or missed patches. If the passenger blade taps the A-pillar or the blades touch, stop: one side has the wrong length.

TORQUE

ezcarfix.com