2002-2007 Buick Rendezvous - Wiper Blade

2002-2007 Buick Rendezvous | Easy | 15-20 minutes | $81 DIY

TOOLS

Clean rag or towel Windshield washer fluid (top up the reservoir if low)

PARTS

Driver wiper blade, 24" Bosch 24A $32.99
Passenger wiper blade, 22" Bosch 22B $32.99
Rear wiper blade, 16" $14.99

STEPS

1. **Confirm the 24, 22, and 16-inch sizes and buy the blades - The 2002-2007 Rendezvous takes** a 24-inch blade on the driver’s side, a 22-inch blade on the passenger side, and a 16-inch blade on the rear liftgate glass. Buy all three before you start - the rear blade wears out just like the fronts.
2. **Park the wipers in the normal off position - Switch the wipers off, turn the ignition** off, and pull the key so the wipers cannot move while your hands are near the arms. Work on level ground with the car in park and the parking brake set.
3. **Remove the old driver-side blade from the J-hook - Lift the driver’s wiper arm off the** windshield until it stands up on its own. If it is stuck from years of weather, rock it gently side to side while pushing toward the arm tip - never yank it.
4. **Prep the new 24-inch driver blade - Take the new 24-inch blade out of the sleeve and pull** off any plastic protective caps from the rubber edge. Lay the old and new blades side by side to confirm the 24-inch length matches before it goes on the car.
5. **Install the new blade and verify the lock - Slide the center of the new blade onto the** open end of the J-hook until you hear and feel a click, then fold the blade back flat against the arm and give it a firm tug to confirm it cannot slide off.
6. **Repeat on the passenger side and the rear wiper - Do the same J-hook swap on the** passenger side with the 22-inch blade - this is the one people mix up, so double-check you are not putting the 24-inch blade here.
7. **Test all three blades with washer fluid - Run the washer so fluid sprays ahead of the** blades - never test dry. Each blade should sweep streak-free with no skipping; the rear washer should wet the liftgate glass. Smearing? Reseat the locking tab; check for a shipping cap on the r...

TORQUE

ezcarfix.com