2024-2026 Chevrolet Equinox EV - Wiper Blade

2024-2026 Chevrolet Equinox EV | Easy | 15-20 minutes for all three blades | $81 DIY

TOOLS

Tape measure or ruler Microfiber cloth and glass cleaner Folded towel (to cushion the windshield under a bare arm)

PARTS

Driver wiper blade, 30" Bosch 30A $32.99
Passenger wiper blade, 22" Bosch 22B $32.99
Rear wiper blade, 12" $14.99

STEPS

1. **Confirm the blade sizes from the owner's manual - 30, 22, and 12 inches - Use the** owner's-manual sizes: 30-inch driver, 22-inch passenger, 12-inch rear. Many aftermarket kits list wrong sizes (26+24+11, copied from the gas Equinox). The fronts use a vehicle-specific top-lock connector - standard J-hooks don't...
2. **Move the front arms up from the park position - No service mode here: push each arm up** the windshield by hand until it clears the hood, working near the hinge - don't yank. The fronts overlap and wipe in opposite directions. Lay a folded towel under each arm on the glass.
3. **Remove the old 30-inch driver-side blade - Find the small latch mid-housing on the** top-lock connector, release it, and slide the 30-inch blade off - study the attachment first, or photograph it. Keep your other hand on the arm throughout; at 30 inches it's long, springy, and will...
4. **Install the new 30-inch driver-side blade - Slide the new 30-inch blade on until the** latch clicks, then pull firmly to confirm the lock - a half-latched 30-inch blade can release at highway speed. Lower the arm by hand; don't let it snap. Check the blade lies flat for its full len...
5. **Replace the 22-inch passenger-side blade - Fit the 22-inch passenger blade the same way,** tug-testing the lock. The overlapping wipers sweep toward each other, so wrong lengths collide mid-sweep. At rest, leave a small gap between the blades - touching means something's wrong (see...
6. **Replace the 12-inch rear wiper blade - Lift the rear arm off the glass, release the** mid-blade latch, and slide the 12-inch blade off. Push the new one up until it clicks, tug to verify, and lower gently. Service the rear on the same schedule as the fronts.
7. **Test the wipers and check arm alignment - Run the washers on low and high plus the rear** wiper: silent sweeps, no streaks, chatter, or blade contact. Arm misalignment is a known Equinox EV issue needing a wiper-arm puller - don't DIY it. Clashing blades left alone leave unwiped b...

TORQUE

ezcarfix.com