# 2017-2025 Chrysler Pacifica - Replace Cabin Air



**2017-2025 Chrysler Pacifica | Easy | 15-20 minutes | $20 DIY**

**TOOLS**

Flathead Screwdriver  Phillips Head Screwdriver  Socket Wrench Set  10mm Socket  Trim Removal Tool  Flashlight  Gloves  Safety Glasses

**PARTS**

Cabin Air Filter PC99238X $20.00

## STEPS

1. **Detach tether - The 2017-2025 Chrysler Pacifica cabin filter is behind the glovebox.** You'll need: new cabin filter (Chrysler OE 68308950AB). Open the glovebox partially. This tether is Pacifica-specific - don't skip it.
2. **Remove the hush panel - With the glovebox down, you'll see the hush panel under the dash.** Remove the hush panel fasteners and remove the hush panel (per AutoZone CAF1957C). Set it aside.
3. **Remove the filter cover - On the passenger side of the HVAC housing, you'll see the cabin** air filter cover. Remove the cover and set it aside. Pull the filter element straight out.
4. **Remove old filter (note floor-pointing arrow) - Pull the old filter straight out. Note** the airflow direction - on the Pacifica, the airflow arrow points TOWARD THE FLOOR (down). This is important - don't install it backwards. The Pacifica's large cabin needs good airflow.
5. **Install new filter (arrow to floor) - Slide the new filter in with the airflow arrow** pointing TOWARD THE FLOOR (down). This is Pacifica-specific - verify against the housing marking. Ensure it's fully seated. Reinstall the filter cover - engage both retaining tabs. The cov...
6. **Reassemble - Reinstall the hush panel - secure the fasteners. Raise the glovebox back up** (push past the travel stops). Reattach the tension tether - slide the black clip back into its slot. Close the glovebox. Replace every 15,000 miles.

ezcarfix.com