2017-2022 Genesis G90 3.3T - Replace Cabin Air

2017-2022 Genesis G90 | Easy | 30 minutes | $25 DIY

TOOLS

Flathead Screwdriver Phillips Head Screwdriver Socket Wrench Set Trim Removal Tool Glove Box Support Rod Removal Tool

PARTS

Cabin Air Filter S12E988 $25.00

STEPS

1. **Unclip dampener (left side) - The 2017-2022 Genesis G90 3.3T cabin filter is behind the** glovebox. You'll need: new cabin filter. Open the glovebox and empty it. The G90's left-side dampener is the quirk.
2. **Locate the filter case - The G90's filter is in the HVAC housing behind the glovebox. The** owner's manual (p. 3-124) confirms: 'The cabin air filter is installed behind the glove box.' This is consistent across 2017-2023 manuals - same location.
3. **Remove the filter cover - Set the cover aside. The cabin filter is now visible. The G90's** cover pulls toward you - don't push.
4. **Remove the old filter - Pull the old filter out. Note the airflow direction. If the** filter is dirty, that's affecting your G90's luxury climate control. The G90 is Genesis's flagship - the cabin should feel pristine. A clogged filter undermines the luxury exper...
5. **Install the new filter - Slide the new filter in, matching the airflow direction. Ensure** it's fully seated. Reinstall the filter cover - push it back until both sides engage. The cover should sit flush. Verify the filter is properly positioned.
6. **Reassemble and test - Swing the glovebox back up. Close the glovebox. Test the climate** control - the G90's cabin should feel fresh and luxurious. Replace every 15,000-20,000 miles. The G90's left-side dampener arm is unusual - remember it for next time.

ezcarfix.com