2015-2020 GMC Yukon XL - Cabin Air Filter

2015-2020 GMC Yukon XL | Easy | 10-15 minutes | $28 DIY

TOOLS

screwdriver (for the four screws around the lower glove box) small tray or cup to keep the four screws together

PARTS

Cabin air filter for 2015-2020 GMC Yukon XL; verify arrows, size, and VIN/trim fitment $28.00

STEPS

1. **Confirm your truck has a cabin filter - Worth knowing: the previous-generation GMT900** trucks from 2007 to 2014 did not come with a cabin filter from the factory at all, so some owners of older trucks wrongly assume this one lacks a filter too - yours has one.
2. **Remove the four screws around the lower glove box - With the glove box door open, remove** the four screws that surround the lower glove box frame - a plain screwdriver is all you need. Keep the screws together in a cup or tray.
3. **Pull the door and frame out as one assembly - It comes out as one assembly - do not try** to separate the door from the frame. Set it on the passenger seat where it will not get stepped on or scratched.
4. **Open the filter service door - Behind where the glove box sat is the rectangular filter** service door. Release its two tabs with even finger pressure - no tools needed - and swing it open, easing the door so neither tab cracks.
5. **Remove the old filter - Pull the old filter straight out of the housing and note which** way the airflow arrow on its frame points before you toss it - on the K2XX trucks the arrow points down toward the blower.
6. **Install the new filter - Slide the new filter into the housing with the airflow arrow** pointing the same direction as the old one - down into the HVAC box.
7. **Reassemble - Close the service door until both tabs click, refit the glove box frame into** the dash, and reinstall the four screws snugly - firm, but do not overtighten into the plastic.

TORQUE

ezcarfix.com