2022-2025 Infiniti QX60 - Cabin Air Filter

2022-2025 Infiniti QX60 | Easy | 15-25 minutes | $20 DIY

TOOLS
Trim tool or flat screwdriver (optional) Flashlight Gloves Vacuum or rag for debris

PARTS
Cabin air filter 27277-5NA1A $20.00

STEPS

1. **Prepare the QX60 and confirm the filter application - Park on level ground, brake set,** ignition off. The filter sits UNDER the glovebox in the footwell - don't drop the glovebox. Confirm fitment for 2022-2025 (OE 27277-5NA1A). Pinch the filter sides to feed it through the deliberately tight...
2. **Remove the passenger footwell trim panel - Sit in the passenger seat and find the** footwell trim panel, left side near the center console. Pull it straight down and off - it's clip-held - to expose the HVAC housing. Work gently; the clips break easily.
3. **Open the filter door and remove the old filter - Open the filter door - release its** clips. Slide the old filter out, noting the arrow direction. Vacuum the slot - debris collects here with the low intake. Work the clips from one corner; the panel cracks easily.
4. **Install the new cabin filter - Feed the new filter in, arrow matching the original. Pinch** the sides to feed it through the tight opening. It must lie flat with no folds - bypass air defeats the filter. Snap the door shut.
5. **Reassemble and verify HVAC airflow - Refit the footwell panel, pressing firmly so every** clip seats. Start the engine and run the fan through its speeds on fresh air - strong, quiet airflow, no rattling. Vacuum the carpet first so grit doesn't fall in.

ezcarfix.com