2022-2026 Jeep Grand Wagoneer | Easy | 15 minutes | $28 DIY

TOOLS

Flashlight Trim-safe plastic pry tool (for stubborn door tabs only) Small vacuum for the filter slot

PARTS

Cabin air filter for 2022-2026 Jeep Grand Wagoneer; verify arrows, size, and VIN/trim fitment $28.00

STEPS

1. **Empty the glove box and note your engine - Empty the glove box. The cabin filter lives** behind it, inside the HVAC case - the same spot across all 2022-2026 Grand Wagoneers, whether yours has the early 6.4L V8 or the later Hurricane 3.0L twin-turbo. Fitment follows the HVAC case...
2. **Release the damper and lower the glove box - Open the glove box, release the damper arm** from its pin, and ease the box past its stops. Support the heavy box with one hand so it doesn’t slam the dash stops; the rectangular filter door sits behind it.
3. **Unclip the rectangular filter door - Release the door’s small tabs the way they’re** designed to move - press inward or slide, never pry outward. A snapped tab means the door never seals properly again, so pull gently toward you and set the door aside.
4. **Slide the filter cassette out - Grip the cassette frame and pull it straight out. Before** tossing it, read the airflow arrow on the frame - mirror that direction with the new filter. Check the empty slot for leaf fragments and dust and wipe it clean.
5. **Seat the new filter with the arrow aligned - Slide the new filter in with its airflow** arrow matching the old one’s direction and push it fully home until the frame sits flush - even a quarter-inch short leaves a bypass gap you’ll hear as a whistle at high fan speeds.
6. **Re-clip the door and raise the glove box - Press the door back in until every tab clicks** - a door proud on one corner leaks air. Lift the glove box past its stops, reattach the damper arm, then open and close the box twice: it should glide down under damping, not drop.
7. **Start up and test the three-row climate system - Start the engine and run the climate at** full fan through front and rear modes. The rear zones share this filter, so weak rear airflow means the cassette isn’t seated. Listen for whistling or rattling from behind the dash; then log the date...

TORQUE

ezcarfix.com