2019-2023 Volkswagen Arteon - Wiper Blade

2019-2023 Volkswagen Arteon | Easy | 10-15 minutes | $66 DIY

TOOLS

Tape measure Glass cleaner and clean rag
Pin or needle for washer nozzles

PARTS

Driver wiper blade, 26" Bosch 26A $32.99
Passenger wiper blade, 19" Bosch 19B $32.99

STEPS

1. **Buy the right blades for an Arteon - Your Arteon takes a 26-inch blade on the driver side** and a 19-inch blade on the passenger side - 26/19 is confirmed across every fitment catalog for the 2017-2023 car. These are not J-hooks: the Arteon uses VW's slim push-button connec...
2. **Move the wipers to the service position - The blades park below the hood's trailing edge,** so they must be moved before you can lift them. This is VW's standard service-position sequence. Skip it and the blades stay trapped under the hood lip.
3. **Release the driver blade from its push-button clip - Fold the driver arm out until it** stands off the glass. Press with your thumb and slide the blade downward, away from the arm - it releases with a light pop. Keep a firm grip on the arm with your other hand the whole time.
4. **Snap the new 26-inch blade onto the driver arm - Hold the new 26-inch blade up to the arm** and line up the push-button connector with the arm's rectangular tongue. Slide the blade upward onto the tongue until the button clicks out through its window - you will feel it seat positively. G...
5. **Swap the 19-inch passenger blade - The passenger side uses the identical push-button** release: press the button, slide the old blade down and off. The only difference is the 19-inch length - noticeably shorter than the driver's 26 inches. This asymmetry is by design, so do...
6. **Clean the glass and inspect while the arms are up - With no rear wiper to service, use** this moment to inspect what the blades hide. Check the rain sensor behind the rearview mirror - a small dark module bonded to the glass that drives the auto-wipe function; make sure its gel pad area is...
7. **Test the wipers and know when to replace again - Lower both arms fully, switch the** ignition on, and take the wipers off the service position by flicking the stalk - they'll park themselves. Run them on low and high, then test the washer. Replace blades every 6 to 12 months.

TORQUE

ezcarfix.com