2010-2017 Volvo XC60 - Wiper Blade Replacement

2010-2017 Volvo XC60 | Easy | 15-20 minutes | $81 DIY

TOOLS
Microfiber cloth

PARTS
Driver wiper blade, 26" Bosch 26A $32.99
Passenger wiper blade, 20" Bosch 20B $32.99
Rear wiper blade, 14" $14.99

STEPS

1. **Confirm the sizes and buy the blades - 26-inch driver, 20-inch passenger - buy one of** each. Rear is 14 inches on 2013-2017; 2010-2012 charts list 15, so measure the old rear. Front arms use a 19mm top-button connector - buy Volvo top-button blades, not generic J-hook.
2. **Park and prep - no service position needed - Wipers park on the glass - no service** position, just lift the arms. Ignition off, wiper stalk off. Work one side at a time so the 26-inch and 20-inch blades never get mixed up.
3. **Release the old driver-side blade - Lift the driver-side arm up. Find the release button** or locking tab on the center connector and press it while sliding the blade down off the pin. Hold the bare arm - it can snap back and crack the windshield.
4. **Prep the new 26-inch blade - Remove the protective sleeve; don’t touch the rubber wiping** edge. Confirm the 19mm top-button adapter is already fitted - the clip must click over the arm’s button. Hold old and new side by side to confirm the 26-inch length matches.
5. **Slide the new blade on and check the lock - Slide the new 26-inch blade onto the arm’s** pin until the clip clicks. Tug it firmly along the arm - no sliding, rocking, or rattling. If it moves, reseat it until the click is unmistakable. Lower the arm gently onto the glass.
6. **Do the passenger side and the rear blade - Repeat for the 20-inch passenger blade. Press** the tab and slide the old blade off its snap-claw or U-clip (2016-2017 snap-claw, earlier U-clip), then snap the new 14-inch (or 15-inch) on. Support the rear arm so it can’t snap back onto t...
7. **Test with washer fluid - Start the car and spray the washers on all wiper speeds. Each** blade sweeps clean - no streaks, skips, or chattering. Run the rear washer and wiper; the rear blade should clear its arc. Re-seat any chattering blade - its clip didn’t ful...

ezcarfix.com