

2010-2016 Land Rover Discovery | Easy | 15-30 minutes

TOOLS

Plastic trim tool Screwdriver set
(glovebox fasteners) Small vacuum or damp
cloth Flashlight

PARTS

Cabin air filter (Corteco 80000361 / CUK
2747 application)

STEPS

- 1 Empty the glovebox and prepare - The video is FCP Euro's cabin filter replacement on a 2010-2016 Land Rover LR4 - the LR4 is the US-market name for the Discovery 4, an exact match for this hub. Park the Discovery, switch the ignition off, and open the passenger-side f...**
- 2 Remove the glovebox - Following the video's glovebox-removal sequence, release the glovebox damper arm and squeeze the sides past their stops to drop the glovebox fully down. Support it as it comes free rather than letting it hang by the wiring for the glovebox...**
- 3 Open the housing and remove the old filter - Unclip or unlatch the filter housing cover and set it aside. Note the airflow direction arrows on the old filter's frame before pulling it out. Slide the old filter straight out, keeping it level so trapped leaves and dust do not spill int...**
- 4 Clean the filter housing - Vacuum the empty filter housing and wipe the sealing surfaces clean. The video notes these filters collect twigs, leaves, and debris that cause poor smells - remove all of it. Check the housing for dampness that could indicate a blocked...**
- 5 Install the new filter correctly oriented - Slide the new filter into the housing with its airflow arrows pointing the same direction as the old filter. Press it fully home so the perimeter seals with no bypass gaps. Refit the housing cover until its clips or latches engage positive...**
- 6 Reinstall the glovebox - Lift the glovebox back into position, re-engage the side stops and damper arm, and reconnect the glovebox light wiring if disconnected. Confirm the glovebox opens, closes, and latches smoothly with no binding.**
- 7 Test the HVAC and finish - Start the engine and run the climate system on fresh-air mode at high fan speed. Verify strong, clean-smelling airflow from the dash vents and the absence of the musty odor the old filter caused. Return the glovebox contents.**